TRANS

BOA-516 series

Low Voltage Bi-Level Occupancy Sensor

INSTALLATION INSTRUCTIONS







w/Lens D



w/Lens F



w/Lens G

OVERVIEW

The BOA-516 series member of the TRANS family is a low voltage passive infrared occupancy sensor designed to provide 0-10V analog output for occupancy based, multimode bi-level LED lighting control. Depending on the selected mode, this sensor will provide various control voltages for dimmable driver according to the occupancy status and ambient light level change.

This PIR occupancy sensor employs a cutting edge quad element pyroelectric infrared sensor to provide omni-directional sensing capability of occupant's presence and motions. An advanced digital ambient light sensor is integrated to provide smart day-night judgment for bi-level or daylight harvesting control. The sensor offers 8 different control modes via rotary DIP switch selection.


Same as all sensors in the TRANS family, the BOA-516 series is available with various mounting options and interchangeable lenses. This feature provides a second-to-none design and installation flexibility. The sensor is designed to operate in the coldest of environments, down to -40°C/°F.

A AVERTISSEMENT & PRUDENCE

- Ne PAS toucher la fenêtre carrée de capteur infrarouge sous l'ensemble de l'objectif.
- Convient gamme de câblage 16-20 AWG en cuivre massif seulement.
- Ouvrir Type commutateurs optoélectroniques.

INSTALLATION NOTES

- 1. The sensor is more sensitive to the movements. "crossing" the detection zones than "toward" or "away" the sensor unit. To obtain better sensitivity, avoid placing the sensor in line with occupant path, if possible.
- 2 The closer the movement is to the sensor, the more sensitive the sensor is. The higher the sensor is installed, the larger movement is required to be detected.
- 3. Ensure to place the sensor at least at 1.5m (5 ft.) away from air supply ducts as rapid air flow may cause false activations.
- 4 The sensor cannot "see" the movements behind obstacles, such as furniture, shelf, glass or partition. As a general rule, each occupant should be able to clearly view the sensor unit.
- 5. For open office areas with partition which could block the sensor view to occupant movements, it is best to place the sensors over the intersection of multiple workstations. For large areas of open office or space, place multiple sensors so that there is overlap coverage with each adjacent sensor.





A WARNING & CAUTION

- Do NOT touch the square window of infrared sensor under the lens assembly.
- Suitable wiring range 16-20 AWG solid copper wire only.
- Open Type Photoelectric Switches.













^{*}More lens options are available for this sensor. Please refer to the Lens Datasheet for more details.

WIRING DIAGRAM BALLAST/ **BOA-516** LIGHT SOURCE LED DRIVER 12~24VDC POWER SUPPLY MODE (TEST) **SENSOR SETTINGS** TIME (Factory set) (10 minutes) (OFF) 2 7

TIME 1' 3' 5' 10' 15' 20' 30' DIM OFF 4V 1.5V 2V 2.5V 3V 5V

3

5

6

Factory Set

Delay Time

POS.

1

The BOA-516 series offers 7 different delay time settings via Accu-Set potentiometer. The light will remain ON if sensor detects occupant's movement before the set delay time expires. The Accu-Set potentiometer will provide accurate delay time as the arrowhead pointed.

Dim Level

The BOA-516 series offers 7 different dim level settings via Accu-Set potentiometer. The LED light will be dimmed as the level set when condition of selected control mode applies. The Accu-Set potentiometer will provide accurate dim level as the arrowhead pointed.

TESTING

- 1. Set the control mode switch pointing to position "A".
- indicate sensor detection as well.
- * Depending on the lens type ordered and mounting

Control Mode

The BOA-516 series features 8 different control modes selectable via rotary DIP switch. Please refer to the following description and select the desired control mode.

NOTE: Ensure to set the DIP switch at "click" position while setting the control mode.

Mode	Sensor Control Description	
Α	 Turn on the light for 5 seconds at every motion detected. Dim the light for 10 seconds and then turn off. 	
В	 Ambient light sensor is disabled with this mode. Dim the light to low level as DIM set all time under vacancy. Turn the light to full-ON per delay TIME set under occupancy. 	
С	 Light off while ambient light is higher than 50 lux. While ambient light is lower than 20 lux, dim the light to low level as DIM set under vacancy. Turn the light to full-ON per delay TIME set under occupancy. 	
D	 Light off while ambient light is higher than 130 lux. While ambient light is lower than 80 lux, dim the light to low level as DIM set under vacancy. Turn the light to full-ON per delay TIME set under occupancy. 	
E	 Light off while ambient light is higher than 600 lux. While ambient light is lower than 500 lux, dim the light to low level as DIM set under vacancy. Turn the light to full-ON per delay TIME set under occupancy. 	
F	 Light off while ambient light is higher than 50 lux. While ambient light is lower than 20 lux, light stays off under vacancy. Turn the light to full-ON per delay TIME set under occupancy. When delay time elapse, dim the light to low level as DIM set for 10 minutes as Time Off delay. Turn the light to full-ON per delay TIME set if sensor detects occupancy during Time Off. Turn the light off if no occupancy detected during Time Off delay. 	
G	 Light off while ambient light is higher than 130 lux. While ambient light is lower than 80 lux, light stays off under vacancy. Turn the light to full-ON per delay TIME set under occupancy. When delay time elapse, dim the light to low level as DIM set for 10 minutes as Time Off delay. Turn the light to full-ON per delay TIME set if sensor detects occupancy during Time Off. Turn the light off if no occupancy 	

detected during Time Off delay.

for 10 minutes as Time Off delay.

detected during Time Off delay.

vacancy.

н

1. Light off while ambient light is higher than 600 lux.

2. While ambient light is lower than 500 lux, light stays off under

3. Turn the light to full-ON per delay TIME set under occupancy.

4. Turn the light to full-ON per delay TIME set if sensor detects

When delay time elapse, dim the light to low level as DIM set

occupancy during Time Off. Turn the light off if no occupancy

Mode Operation Chart MODE Output(%) NIGHT 100 B (OSO) DIM DELAY DELAY 100 C (OSLA) D (OSMA) DIM DELAY E (OSHA) 100 F (OSLATO) G (OSMATO) DIM DELAY 10 MIN H (OSHATO)

SPECIFICATIONS

Motion

Power supply	12~24VDC
Current Drain	8mA @ 24VDC, load OFF
Infrared sensor	Omni-directional quad element pyroelectric
Sensor output	0-10V analog
Detectable speed	0.15~3m/sec. (0.5~10 ft./sec.)
Mounting height	Subject to the lens type applied
Detection range	Subject to the lens applied and height
Ambient light level	L:20~50 lux, M:80~130 lux, H:500~600 lux
Low dim level	0/1.5/2/2.5/3/4/5V selectable
Delay time setting	1'/3'/5'/10'/15'/20'/30' selectable
Time-off delay	10 min., TO modes only
Op. humidity	Max. 95% RH
Op. temperature	-40°C~55°C (-40°F~131°F)
Dimensions	Ø60 x H37mm (Ø2.36"x H1.45")

IR-TEC International Ltd. warranties this product to be free of defects in materials or workmanship for a period of five years from date of shipment. There are no obligations or liabilities on the part of IR-TEC International Ltd. for consequential damages arising out or in connection with the use or performance of this product or other indirect damages with respect to loss of property, revenue, or profit, or cost of removal, installation or reinstallation.

www.irtec.com



- 2. Walk within the desired range* at normal speed. Light should be switched ON for 5 seconds and dim for 10 seconds whenever sensor detects the movement.
- 3. The LED indicator behind lens assembly will blink to
- height, the sensor could have different sensing coverage as instructed on the LENS DATASHEET attached.